Limit to renew main check valve chests expired 9.34

23 JAN 1935 5E

...d by Chief Engineer Surveyor ..... Received from Chief Engineer Surveyor .....

...EL'S NAME Joyous ex Jameson Rpt. Aug. No. 13355.

...emarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92).

...e of Survey ..... [redacted].

Main check valve chests renewed.

Alterations. New liners fitted to H.P. & J.P. cylinders reducing the diameters from 25" & 41" to 24" & 37" respectively.

A steam compressor fitted.

J.P. & H.P. valves renewed
" " " piston rods & valve rods machined

Condenser enlarged & retubed.

Damage due to striking an obstruction:-
Propeller renewed & screw shaft machined

...t is submitted the vessel is eligible to remain as classed with ...ecord of Survey S/12.34 as recommended.

For R.B. Amend H.P. cylinder dia: to 24"
J.P. " " " 37"

endorsement 4/6/35

In existing engine particulars add "and exhaust turbine driving steam compressor".

Submitted. The Gov. Surveyors be asked to state the Brake Horse power of the exhaust turbine.

D.F. 23.1.35.

W443-0060

© 2020 Lloyd's Register Foundation