Engine Room ..)
Gross Tonnage 1407.36
Less Crew Space 48.76
Less above Crown of)

1st Number .....
Length on deck from after part of stem to fore part of stern post 238.4

Owners The New Zealand
Managers
(...ered in Reg. Book.)
New-Z...

5c,1,8.

F.E. Renewal

Received by Chief Ship Surveyor 28. 11. 08

Received from Chief Ship Surveyor

VESSEL'S NAME Stt. S.S. "Greenbatt" Rpt. Gld. No. 23901

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	2/20"	Proportions
Spar Sheerstrake . .	"	"
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Deep (Bulb angle)	framing, increased on account of large hatchway.

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") as recommended.

✠ 100 A 1 ("Steel")
1 DR (Stt) Well Deck.
W.B = Cell DB a 70' u E&B 32' f 96' 372t FPT 63t APT 94t
FK 4BH Cem. Lloyd's A&CP Q 129' B 10' F 21'

C.A.B. 28/11/08

W446-0001

© 2020 Lloyd's Register Foundation

" Quarter, 'tween Dks., " "
" " in Hold " " Brackets of steel at ship's sides in lieu 7/20.
~~WEB FRAMES, In Fore Body, No. and Spacing~~
" " " ~~Bredth. & Thickness~~

" Angle on ditto.....
" ~~Tie Plates~~ ..... Sheathed
" Deck, Material and thickness Steel
* If Iron or Steel Deck, state if whole or part, and if wood d...

Number. STIFFENER