S. S. "Y O R K S H I R E".

Extract from Liverpool Survey Report No. 86770, dated 25.4.24.

:-:-:-:-:-:-:-:-:-:-:-:-:-:-:-:

Alterations to passenger freeboard line, see Secretary's letters 4th inst. "M", and 24th inst. "M".

The following alterations have now been carried out:- 121 side scuttles in the Awning deck space have been supplied with Malleable cast iron fitted plugs; 2 side scuttles in Engineer's W.C.'s on starboard side have been fitted with deadlights; 8 side scuttles in steering engine house aft have been fitted with special type locking nuts for fastening when closed.

The slop shoot in galley starboard side has been fitted with a valve operated by a balance arm and weight fitted to ensure valve being automatically closed through a 15° list. A water tight cover has been fitted to the slop trough, to be kept closed and secured except when in use. The work has been carried out in a satisfactory manner.

The foregoing alterations have amended the passenger freeboard to 2'-8" below centre of disc.

Noted
7.5.24

© 2020
Lloyd's Register Foundation

W450-0156