Lloyd's Register of Shipping. 6.9500

8A

3 - NOV 1939

by Chief Ship Surveyor ..... Received from Chief Ship Surveyor .....

'S NAME ABBOTSFORD Rpt. NWC. No. 97983

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

of Survey DAMAGE.

The Newcastle Surveyors report this vessel examined afloat on count of damage through collision

Shell side plating & framing aft (55) indented
lifeboat & davit damaged

Permanent repairs have been effected to the
at & davit & Temporary repairs have been effected to the shell plating to their satisfaction,
d the Surveyors recommend permanent repairs to shell plates No. 4 in
heerstrake, No. 4 in 1st and No. 3 in 2nd below sheer (5.5) aft and framing etc
n way at the first opportunity

It is submitted the vessel is eligible to remain as classed
thout record of survey, subject as recommendel.

WAG
3.11.39.

now, subject, etc.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

© 2020 Lloyd's Register Foundation

W472-0182