Attikos

F.E.

Received by Chief Ship Surveyor 17. 2. 06 *Received from Chief Ship Surveyor* .....

VESSEL'S NAME Stm. S.S. "Athenic" Rpt. Sld. No. 22617

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

RETAIN

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Deep (Bulb angle) framing of less depth than required, but compensated by series of web frames.	

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel") as recommended.

RETAIN

✠ 100 A 1 ("Steel")

1 Dr (Stt) 2 to B, deep framing & web frames, 3 Dr Rule.

W.B = Cell DB a 127' u E 21' f 158' 87 6 t DT a 29' 78 4 t FPT 74 t APT 82 t

FK 6 BH Cem. Lloyd's A4 CP P 26' B 100' F 34

C. S.
27/2/06

© 2019 Lloyd's Register Foundation

W478-0111

„ Average space										
BEAMS, Forecastle Deck, ~~Angle~~, Bulb Angle,	9	3½	10	9	3½	10		**Poop Deck Stringer Plate,** breadth & thickness		
								„ Angle on ditto		