Rpt. 8.

(Received at London Office 11 FEB 1929) No. 18168

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 8th of Feb. 1929 When handed in at Local Office ..... 19.... Port of Rotterdam

No. in Reg. Book. 73838 Survey held at Schiedam Date, First Survey 18th of Jan. Last Survey 7th of Feb. 1929 (No. of Visits 3)

on the ~~Wood, Iron or~~ Steel S/S "INCHDAIRNIE."

TONNAGE:— GROSS 6596 UNDER DK. 6202 NET 4024

Built at Kinghorn By whom Kinghorn S.B.C. When YEAR. 1921 MONTH. 5

Owners J. Fletcher Owners' Address Glasgow (if not already recorded in Appendix to Register Book).

Managers ~ Port belonging to Glasgow

Surveyed Afloat or in Dry Dock? both Name of Dock Wilton's Dock Destined Voyage Antwerp

WB=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet

total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 17277 Port Rot.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned or Extended.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A1 L 20		+ LMC 7.29
shelter deck		B.S. 7.29
with freeboard		T.S. Mem 2.20
S.S. Glen Line		

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; being detailed in the body of the report, should be summarised in the form shown below. Whenever the ... of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ... form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

Surveyor has not made a special damage report he is required to state whether he ... is purpose and to whom and why they were declined .....

...ificate herewith Was a damage report made by anyone else? If so, by whom? ✓

...TION AS PER RULE, FOR Part Spec. Survey No. 2.

... has been placed in drydock, bottom and rudder ...mined found in good condition and recoated. ... bottom tanks, fore and afterpeak tanks tested ...sure as required by the rules and found ...d tight. Windlass en^e and found in order. ... steering engine defective, same will be made ... Antwerp. ... steering gears tested in working condition ... in order.

	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
...								
...								
...								

State if Tanks have been examined inside no

State if Tanks now tested yes tight

Bulkheads ..... in A.S. keeper

Ceiling 6

Cement or Asphalt (State which.) 1

Rudder ..... good

Steering gear and its connections ..... like repairs

Windlass ..... good

Have Pumps now been examined and found efficient? ..... not examined

Have Sluice Valves now been examined and found efficient? ✓

Have Watertight Doors now been examined and found efficient? ..... not examined

Have Ventilators and their Coamings been examined and found efficient? ..... yes good

Dblng. Plates under Sounding Pipes not examined

Engine Room Skylights ..... good

Coal Bunkers, Open'gs, Lids, &c. ..... "

Scuppers 4

Cargo Hatchways ..... "

Hatches 6

Planking of Wood Vessels .....

Caulking ditto .....

Treenails ditto .....

Breasthooks & Stemson ditto .....

Transoms, Pointers, & Crutches ditto .....

Timbers of Frame at openings ditto .....

Ditto ditto at other places ditto .....

Stringers, Clamps & Shelfs ditto .....

Salting (State if examined.) ditto .....

Copper, or Y.M. of Wood Vessels ..... ✓ (State if on Felt).

When put on, Month ..... ✓ Year ..... ✓

Boats ..... good

Masts, Yards, &c. 16

Condition, how ascertained ..... (State if wedges removed). no

Sails 6

Equipment letter ..... A 1

Anchors, No. of ..... Complete

Cables (State if now ranged) ..... no

" length ..... ✓ size ..... ✓ (on board)

" Rule length ..... ✓ size ..... ✓

Hawser & Warps ..... not examined.

Standing and Running Rigging ..... good

...ns, Opinion as to Class, Recommendation, &c.:—

...and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ...assed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

...in a fit condition to be towed to Antwerp. ...opinion eligible to be continued as classed ...ecord of Survey 2.29. Subject to ...epairs to the steering engine be carried out at Antwerp.

J. v. Heemskerck

Surveyor to Lloyd's Register of Shipping.

Fees applied for, ... 19.....

Received by me, 13/2/29 19.....

£ 120.00 : :

£ 6.00 : :

£ : :

Committee's Minute ✓ TUE. 12 FEB 1929

Character Assigned Deferred

With Ant. 1/2/29.

FRI. 15 MAR 1929

WED. 3 APR 1929

TUE. 3 DEC 1929

FRI. 4 APR 1930

FRI. 4 JUL 1930

TUE. 8 JUL 19...

Is Certificate required? If so, to be sent to Engine Room.

(The Surveyor's ...)

© 2019 Lloyd's Register Foundation W482-0391