Rpt. 8.

(Received at London Office THU. NOV. 13. 1914 No. 28078

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 17. 11 19 14 When handed in at Local Office Port of Hull

No. in Reg. Book. 634 Survey held at Hull Date, First Survey 17. 10. 14 Last Survey 14-11 1914

on the ~~Wood, Iron or~~ Steel Sc. K: Hercules Master (No. of Visits 9)

TONNAGE:- GROSS 261 UNDER DK. 232 NET 103

Built at Beverley By whom Cook · Welton & Gemmell When YEAR 1903 MONTH 10

Owners Lancashire S.F. Coy. Ltd. (J.A. ROBERTSON MGR) Port belonging to Fleetwood

Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Both Name of Dock St Andrews Destined Voyage Fishing

WB=CellDBorDBa ... feet; uE&B ... feet; f ... feet; total capacity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 27873 Port Liv.

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ... amount of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ... besides being detailed in the body of the report, should be summarized in the form shown below. Whenever the ... placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ... back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and Expired	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1		+LMC 6-11.
STM TRAWLER		BS 6-14
6-14.		
SS. HUL NO. 2-11.		6-14

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

~~damage~~ cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

EPAIRS, OR EXAMINATION AS PER RULE, FOR Condition & New Boiler

Vessel placed on slipway. bottom & rudder cleaned examined and coated.

Now done two floors below boiler fitted with double rev frames, all boiler stools renewed.

Side Bunkers. Port side 9 rev frames fitted with face plates and eight on starbd side ditto.

Side bunker casing renewed port & starbd.

a small part of wood quarter deck renewed port & starbd in way of boiler casing.

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks good
Caulking of Decks "
Waterways "
Seamings "
Beams & Fastenings ✓
Outside Plating good
Caulking of ditto "
Rivets "
Breasthooks & Crutches ✓
Transoms ✓
Frames as above good
Reverse Frames " "
Floors " "
Keelsons " "

Stringers
Inner Bottom Plating
State if Tanks have been examined inside
State if Tanks now tested
Bulkheads
Ceiling
Cement or ~~Asphalt~~ (State which.) Boiler room good
Rudder "
Steering gear and its connections "
Windlass "
Have Pumps now been examined and found efficient? No
Have Sluice Valves now been examined and found efficient? No
Have Watertight Doors now been examined and found efficient? No

Dblng. Plates under Sounding Pipes ✓
Engine Room Skylights good
Coal Bunkers, Open'gs, Lids, &c. "
Scuppers "
Cargo Hatchways "
Hatches "
Planking of Wood Vessels
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto

Copper, or Y.M. of Wood Vessels (State if on Felt.)
When put on, Month Year
Boats good
Masts, Yards, &c. "
Condition, how ascertained from Dk
(State if wedges removed) No ✓
Sails
Equipment letter ✓
Anchors, No. of 3
Cables (State if new ranged) No
" length (on board) / size /
" Rule length / size /
Hawser & Warps good
Standing & Running Rigging "

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of *ss No.* 1-11 and ptND11, &c."

This vessel is eligible in my opinion to remain as classed with fresh record of survey 11-14.

Survey Fee (per Section 23) £ : :
Special Damage or Repair Fee (if any) (per Sec. 20) £ : ✓
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :

Fees applied for, ... 19...
Received by me, ... 19...

W. H. Roberts
Surveyor to Lloyd's Register of British & Foreign Shipping

Committee's Minute ✓ FRI NOV 20 1914

Character Assigned 100A1 Stm Trawler + N.B. 11.14.

W486-0021

10m.1/14—Prentice Ltd.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

If Certificate required? If so, to be sent to

RETAIN

© 2019 Lloyd's Register Foundation