For the information of Surveyors and the Committee only.

Received at ..... Office ..... SEP 29 1938

Lloyd's Register of Shipping.

(Report on Vessel No. 23794 Port Cy.

No. F. 1640 - SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by Askam Engineering Co. Ltd of Newport Mon for the Vessel No. , being built ~~by~~ S/s. 'Akti' of Syra. have been inspected by me as set forth below and found to be, so far as can be seen, sound & free from defects

Forgings or Castings.

Lloyd's No. 1670 (M) 16.9.38

D. Macfarlane 17th Sept. 1938.

	STERN FRAME.	RUDDER ~~FRAME~~. MAIN-PIECE	STEM.
... ...		Iron	
le		Forged	
led			
ns		10¼ to 8¾ x 36 : 10½	
on Inspection ...		Forged. Finished	
en Inspected		15th 16th 17th Sept. 38	
ASTINGS. Standard Test Pieces.			
est— r square inch ...			
on per cent.			
ding Test— efore fracture ...			
t— from ground			
ng Test— according to Rules found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Old arms bored out & shrunk on. Rudder plates riveted. Rudder stock tested with main piece for alignment & found in order.

(if any chargeable) £ 2 : 2 : 0

To be paid at Newport Mon

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

© 2019 Lloyd's Register Foundation

WS33-0246

Survey Fee (per Section 29) Damage £10 : 10 : 0. Fees applied for 28/9/38