No. 8.

(Received at London Office OCT 10 1938) No. 10417

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report September 17th 38 When handed in at Local Office ..... 19.... Port of Calcutta

No. in Reg. Book. 2239. Survey held at Calcutta. Date, First Survey 16.9.38. Last Survey 16.9.38. 19 (No. of Visits 1)

on the ~~Wood, Iron or~~ Steel S.S. "CHEBASSA"

TONNAGE: GROSS 631. UNDER DK. 591. 422.

Built at Belfast By whom Workman Clark & Co Ltd When YEAR. 1907. MONTH. 3.

Owners British India Steam Nav Co. Owners' Address (if not already recorded in Appendix to Register Book).

Managers Port belonging to Glasgow.

Surveyed ~~Afloat or~~ in Dry Dock? Name of Dock King George dock. Destined Voyage

CellDBorDBa feet; uE&B feet; f feet

capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be undertined.

Report, No. 5783 Port Bom

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned since expired.	Machinery and Boiler Surveys (including date of N.B., in any).
+100A1.		+L.M.C.
12.37.		M.S. 2.36.
S.S. Cal & Ms 3 11.31.		S.S. 8.37
S.S. Cal. No 1 . 36.		C.L. 12.37.
NOTED FOR OIL FUEL 3.20 F.P. ABOVE 150° F.		

Special Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters relating thereto.

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

Dd. in dry dock, bottom & rudder cleaned, examined & coated. Cables ranged.

Other decks examined.

Glass & Steering gear examined without opening up found in good order.

Note:- Stern & bos plating damage not dealt with at this time as the vessel is now going to the U.K. for disposal.

Should not detailed recommendations detailed on Rpt 10 of 17-9-38 be included in this Rpt?

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired	✓	✓	✓	✓	✓	✓	✓	✓
Renewed or Repaired in place								

CONDITION OF THE

Hold Good ✓	State if Tanks have been examined inside ✓	Air and Sounding Pipes ✓	Copper, or Y.M. of Wood Vessels ✓ (State if on Felt.) When put on, Month ✓ Year ✓
Decks " ✓	State if Tanks now tested ✓	Dblng. Plates under Sounding Pipes ✓	Boats ✓
" ✓	Bulkheads ✓	Engine Room Skylights Good ✓	Masts, Yards, &c. ✓
Fastenings " ✓	Ceiling ✓	Coal Bunkers, Open'gs, Lids, &c. " ✓	Condition, how ascertained ✓
Plating " ✓	Cement or Asphalt (State which.) ✓	Oil Bunkers ✓	(State if wedges removed) ✓
in way of sidelights ✓	Rudder Good ✓	Scuppers Good ✓	Sails ✓
✓	Steering gear and its connections " ✓	Cargo Hatchways " ✓	Equipment letter a+ ✓
✓	Windlass " ✓	Hatches " ✓	Anchors, No. of 5 ✓
✓	Have pumps now been examined and found efficient? ✓	Planking of Wood Vessels ✓	Chain Locker ✓
✓	Have Sluice Valves now been examined and found efficient? ✓	Caulking ditto ✓	Cables (State if now ranged) Yes. ✓
✓	Have Watertight Doors now been examined and found efficient? ✓	Treenails ditto ✓	" length 270 mean diamr. 2 1/4 in. ✓
✓	Have Ventilators and their Coamings been examined and found efficient? Yes. ✓	Breasthooks & Stemson ditto ✓	(on board) 270 " Rule length 270 size 2 5/16 ✓
✓		Transoms Pointers, & Crutches ditto ✓	Hawser & Warps ✓
✓		Timbers of Frame at openings ditto ✓	Standing and Running Rigging ✓
✓		Ditto Ditto at other places ditto ✓	
✓		Stringers, Clamps & Shelfs ditto ✓	
✓		Salting (State if examined.) ditto ✓	
✓			
✓			
✓	