Rpt. 8.

(Received at London Office 24 FEB 1934) No. 3838

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 8th Feb. 1934 When handed in at Local Office 8th Feb. 1934 Port of Montreal

No. in Reg. Book. Survey held at Quebec P.Q. Date, First Survey 24th Jan. Last Survey 27th Jan. 1934 (No. of Visits 2)

26067 on the ~~Wood, Iron or~~ Steel s.s. "Fraternity"

RETAIN

TONNAGE:— GROSS 676 UNDER DK. 460 281

Built at St. Glasgow By whom Murdock & Murray When 1903 - 11 (YEAR. MONTH.)

Owners A. Furniss Ltd. Owners' Address ✓ (if not already recorded in Appendix to Register Book).

Managers " " Port belonging to Quebec

Afloat or in Dry Dock? Afloat Name of Dock Outer Basin Destined Voyage ✓

BorDBa ... feet; uE&B ... feet; f ... feet

ty ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

...erations in the existing records should be underlined.

...l has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ...ined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ...s inner bottom plating, especially in the boiler space.

...ort, No. 3721 Port Mtl

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. ✱ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Annual Cover expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A.1. 1931		+ h.m.c. 3-29
A.1 Mtl. 2nd N.S. 4-29		A.1 6-31. 5-33
		A.1. 6-33

...gs, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...rs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ... Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ...ng detailed in the body of the report, should be summarised in the form shown below. Whenever the ... Anchors or Chains is reported the particulars should be clearly stated in the space provided on ...s form. State also the dates and initials of any letters respecting this case.

...s where the Surveyor has not made a special damage report he is required to state whether he ...ervices for this purpose and to whom and why they were declined ✓

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

✓ Was a damage report made by anyone else? If so, by whom? ✓

...EXAMINATION AS PER RULE, FOR Damage stated to have been sustained through ...untering ice below the Lower Traverse in the St. Lawrence River and ...ing the vessel to break her port anchor cable with the loss of one hundred ... thirty fathoms of cable and port bower anchor.

...age:- Port bower anchor to be supplied and fitted.

One hundred and thirty fathoms of stud link 1 1/8" dia. cable to be supplied and fitted.

RETAIN

...AMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
... ...								
...d Faired or Repaired								
...epaired in place								

...TION OF THE

...ing

State if Tanks have been examined inside
State if Tanks now tested
Bulkheads
Ceiling
Cement or Asphalt (State which.)
Rudder
Steering gear and its connections
Windlass
Have Pumps now been examined and found efficient?
Have Sluice Valves now been examined and found efficient?
Have Watertight Doors now been examined and found efficient?
Have Ventilators and their Coamings been examined and found efficient?

Dbing. Plates under Sounding Pipes
Engine Room Skylights
Coal Bunkers, Open'gs, Lids, &c.
Scuppers
Cargo Hatchways
Hatches
Planking of Wood Vessels
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto Ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto

Survey confined to Engines

Copper, or Y.M. of Wood Vessels (State if on Felt).
When put on, Month ... Year
Boats
Masts, Yards, &c.
Condition, how ascertained (State if wedges removed)
Sails
Equipment letter
Anchors, No. of
Cables (State if now ranged)
" length ... size (on board)
" Rule length ... size
Hawser & Warps
Standing and Running Rigging

RETAIN

Observations, Opinion as to Class, Recommendation, &c.:—

...te clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ...y, thus, for example:—"...to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of ...24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

...his vessel is in good condition, Eligible in my opinion to remain ... classed without fresh record of survey, subject to one hundred ...d thirty fathms. of cable and one bower anchor being supplied before the ...ening of navigation.

...section 29) ... £ :

...r Repair Fee (if any) ... £ : 4 35 00

...es (if chargeable) ... £ : 26 00

...urveyor's Fee (if any) ... £ :

Fees applied for, 8th Feb. 1934
Received by me. ... 19

Geo Allan
Surveyor to Lloyd's Register of Shipping.

FRI. 19 JUL 1935

Committee's Minute TUE. 6 MAR 1934 FRI. 6 APR 1934 FRI. 10 AUG 1934

Character Assigned Deferred for Comp. Equip & hot. | Deferred Work mfl | Deferred ...

(The Surve...)

Is Certificate required? If so, to be sent to ...

Lloyd's Register Foundation