WB=CellDBorDBa feet; aLgB feet; T feet;
total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be precisely as in Register Book.)

N.B. All alterations in the existing records should be underlined.

CHARACTER.

5c.10,15.

3

Received by Chief Ship Surveyor _____ Received from Chief Ship Surveyor MAR 1921

VESSEL'S NAME Steel S.S. "HAMMERSHUS" Rpt. Cpr. No. 6073.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey Completion of 2nd S.S. No. 1 AND DAMAGE.

Damage through Striking quay wall. (Class is subject to permanent repairs being effected

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.Plates	Dk.Plates
Renewed							
Removed and faired or repaired.....	3						
Faired or repaired in place.....	3	3				1	

Other items:-

Minor repairs effected.

See Below

The 2nd S.S. No. 1 has also been ~~held~~ completed and following repairs done due to wear and tear:-

Some deck plating renewed under donkey boiler, bulkheads in way repaired, bottom & rudder cleaned & recoated & minor repairs effected.

It is submitted the vessel is worthy to remain classed with record of Survey 1,21 Cpr and notation of S.S. Cpr No 1-19 as recommended, without special condition re permanent repairs.

100 A.1. Spar Dk.
1,21 Cpr.
S.S. Cpr. No 1-19.
} Without &c.

ACB 28-2-21

W608-0187

© 2021 Lloyd's Register Foundation

Transfer Ink
write on or below

Survey Fee (per Section 28) £150.00 : Fees applied for, 16-2-21