Contoron

1

Sent to Chief Surveyors 18 . 1 . 09 Received from Chief Surveyors

VESSEL'S NAME Stt. S. S. "Harford" Report Nwc. No. 55990

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in conection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey First entry ~~When due~~

It is submitted the Newcastle Surveyors be requested to explain how the moulded depth can be 28'-3", if the depth from the top of floors to top of upper deck beams is 25'-8½", the depth of center girder 44", and the round of beam 12½" as stated by them.

Lr. 16.1.09
Ansd 18.1

C. N. J.
18/1/09

© 2021 Lloyd's Register Foundation

W657-0166