5c,10,30.

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

11th November, 1931.

Dear Sirs,

s.s. "PETSAMO".

I have to confirm your cablegram of the 10th instant respecting the above steamer, decoded as follows:-

"Petsamo. Referring to your cable of yesterday regarding main boilers steel plugs caulked from MUECI (?MNECI - outside) cannot be removed unless disturb threads in holes necessitate SAXAN (? SAXAW - still) larger plugs STOP Buttstraps specially examined internally and externally and found in good condition STOP Owners most urgently request not to remove plugs Burmeister consider fitting of rivets most unsatisfactory. Plans forwarded today"

and have to acquaint you that the matter is receiving attention.

The plans referred to in the above cablegram are awaited.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

COPENHAGEN.

© 2020 Lloyd's Register Foundation

W69-0174