LENGTH on Deck / er Rule	Feet.	Inches.	BREADTH— Moulded	Feet.	Inches.	DEPTH, ACTUAL—Top of Floors to top of Upper Dk. Beams / Do. do. do. do. Main Dk. Beams			
	379	0		48	9		25	8 4	No. of Decks with flat No. of Tiers of Beams
							17	8 3 4	

Moulded depth, ft. 28 ins. 5 To Upper Dk. Round of Upper Dk. Beam, Actual

(3m,6,4.)

eived by Chief Ship Surveyor ..... *Received from Chief Ship Surveyor* .....

SSEL'S NAME Str. S.S. "Wray Castle" Report Sed. No. 219 52

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

ture of Survey First Survey

It is submitted that before this case receives the consideration of the Committee, the Sunderland Surveyors should be written to and reminded that the classification of this vessel is being delayed owing to the consent of the Owners to the supplying of three 90 fathom lengths of 3½" steel wire hawsers not having yet been obtained in accordance with the Secretary's letter of the 29th August. The Surveyors should be requested to state what steps have been taken to obtain the consent in question.

Lr: to Sld. 26/9/04

C. H. J. 26/9/04

© 2020 Lloyd's Register Foundation
W695-0227

,, ,, ,, No. of Side Stringers ,, ,,	–	–	–	–	–	–	LONGITUDINAL ,, in deep tank	
Size of Angle or Tee Bars to Web-Frames	6½	4½	11	6½	4½	11	Are the outside Plates doubled two spaces of Frames in length?	

NERS.

Vertical.	
Size. Inches.	Spacing Inches.
Flanged 30	