Rpt. 8. (Received at London Office 26 FEB 1915) No. 77518

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 25. 2. 1915 When handed in at Local Office 26 FEB 1915 Port of London

No. in Reg. Book. Survey held at London Date, First Survey 21st Jan. Last Survey 25th February 1915 (No. of Visits)

Supt. 6 on the ~~Wood, Iron or~~ Steel S.S. "Frostburg" Master - Collier

TONNAGE:— GROSS 6342 UNDER DK. 5817 NET 3944

Built at Kiel By whom "Howaldswerke" When 1914 - 6 (YEAR. MONTH.)

Owners H. M. India Office Port belonging to Bremen

Owners' Address (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Surrey C. Dk Destined Voyage Admiralty Service

B=CellDBorDBa ... feet; uE&B ... feet; f ... feet;
al capacity ... tons. FPT ... tons; APT ... tons; MT ... feet ... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ... tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ...ers, and of the inner bottom plating, especially in the boiler space.

ast Report, No. 14138 Port Ham

...iodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...use of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ... account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ...d besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the ...placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ... back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned or now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠100 A1 Shelter dk		✠L. M.C. 6.14
with freebd. 6.14		T. S. 6.14

Society's Freeboard (if assigned) as painted on Ship and now verified ... ft. ... ins.

...damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were ...declined? Yes, issued Was a damage report made by anyone else? If so, by whom? Yes, Underwriter Surveyor

...PAIRS, OR EXAMINATION AS PER RULE, FOR Damage sustained by collision with S.S. "Harburn" on the 1st January 1915 off Gravesend, also by damage at some unknown ...ales.

...ork done: Vessel examined afloat. Repairs due to collision with S.S. "Harburn"
Port Quarter: One sheer strake plate, one in strake below and one in second below sheer (3) all renewed. Four frames cropped and part renewed, two faired in place. Two half beams renewed, two repaired in place. Margin, waterway and beading ...ars renewed. Deck (teak) partly renewed and numerous minor repairs to deck ...ittings.
Starboard side damage: Two shell plates in 2nd strake below and two in 3rd & 4th strake ...d three frames set in and one transverse frame fractured. This damage now temporarily repaired ...fractured frame strapped and rivets and shell plating overhauled & made tight.

...MARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
... Renewed	3	4 Pr	.	.	2 Half	.	.	Teak deck part renewed
... Removed and Faired or Repaired	.	1	.	.	.	.	.	margin waterway & beading
... Faired or Repaired in place	.	2	.	.	2	.	.	bars renewed.

...ENT CONDITION OF THE

...g of Decks ... Stringers ... Deads. Plates under Sounding Pipes ... Copper, or Y.M. of Wood Vessels ... (State if on Felt.)
...ways ... Inner Bottom Plating ... Engine Room Skylights ... When put on, Month ... Year ...
...gs ... State if Tanks have been examined inside ... Coal Bunkers, Open'gs, Lids, &c. ... Boats ...
...& Fastenings ... State if Tanks now tested ... Scuppers ... Masts, Yards, &c. ...
... Plating ... Bulkheads ... Cargo Hatchways ... Condition, how ascertained ...
...g of ditto ... Ceiling ... Hatches ... (State if wedges removed) ...
...ooks & Crutches ... Cement or Asphalt (State which.) ... Planking of Wood Vessels ... Sails ...
...ns ... Rudder ... Caulking ditto ... Equipment letter ...
... Frames ... Steering gear and its connections ... Treenails ditto ... Anchors, No. of ...
...sons ... Windlass ... Breasthooks & Stemson ditto ... Cables (State if now ranged) ...
... Have Pumps now been examined and found efficient? ... Transoms, Pointers, & Crutches ditto ... „ length ... size ...
... Have Clyde Valves now been examined and found efficient? ... Timbers of Frame at openings ditto ... (on board) „ Rule length ... size ...
... Have Watertight Doors now been examined and found efficient? ... Ditto ditto at other places ditto ... Hawser & Warps ...
... Stringers, Clamps & Shelfs ditto ... Standing & Running Rigging ...
... Salting (State if examined.) ditto ...

Surveyed in dock to ascertain extent of damage to vessel above waterline. Vessel subsequently loaded & proceeded partly loaded.

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of *ss No.* 1–11 and ptND11, &c."

This vessel as far as seen is in an efficient condition and eligible to remain as classed, subject to permanent repairs being carried to Starboard Side at the first convenient opportunity.

...vey Fee (per Section 28) Damage Reports £ 6 : 6 : 0
...cial Damage or Repair Fee (if any) (per Sec. 28) " £ 3 : 3 : 0
...velling Expenses (if chargeable) Sunday Survey £ 2 : 2 : 0
...ond Surveyor's Fee (if any) £ : :

Fees applied for, 26th Feb 1915
Received by me, 2. 3 1915

C. R. Hughes
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRI. MAR. 5—1915 TUE. APR. 20. 1915

Character Assigned as now subject.

(The Surveyors) To certificate required, if so, to be sent to

© 2020 Lloyd's Register Foundation W789-0139