Wrecked. 8. 10

Rpt. 8.

(Received at London Office WED. 30 DEC 1908 No. 61953.

REPORT of SURVEY for REPAIRS, &c.

29 DEC 1908

Date of writing Report 28-12 1908 When handed in at Local Office ..... 19..... Port of LIVERPOOL

No. in Reg. Book. 510 Survey held at Fleetwood Date, First Survey 11 Dec 5 Last Survey 11 Dec 1908 (No. of Visits .....)

on the ~~Wood, Iron or~~ Steel S.S. "VIVO" Master Collinson

TONNAGE:— GROSS 270 UNDER DK. 249 NET 103

Built at Selby By whom Cochrane & Sons When 1908 8 (YEAR. MONTH.)

Owners Grant's Stm Fishing Co Port belonging to Fleetwood

Owners' Address ..... (if not already recorded in Appendix to Register Book).

Surveyed ~~Afloat or~~ in Dry Dock? ..... Name of Dock Slipway Destined Voyage Fishing

WB=Cell D Bor D Ba ..... feet; uE&B ..... feet; f ..... feet; total capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 20448 Port Hull

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1		+ LMC
Stm Trawler		8-08
8-08		

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Offered not required also whether any damage report was made, and, if so, by whom? Mr Sleight.

REPAIRS, OR EXAMINATION AS PER RULE, FOR damage by grounding.

Vessel examined on slipway, plating & frames on both sides of vessel's bottom, amidships, found set up.

Repairs. Starboard side. One plate in garboard strake (A) & one in B strake faired in place.

Port side. One plate in A strake, one in B strake & two in C strake removed & faired, landing edges of two plates in D strake faired in place. Nine frames faired in place.

Five floors cut off & now renewed, one hold pillar removed & faired.

If so, is the Report sent now, or when will it be sent?

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed				5				
Removed and Faired or Repaired	4							
Faired or Repaired in place	4	9						

PRESENT CONDITION OF THE

Decks: Good
Caulking of Decks: "
Waterways: "
Coamings: "
Beams & Fastenings: "
Outside Plating: "
Caulking of ditto: "
Rivets: "
Breasthooks & Crutches: Not seen
Transoms: "
Frames: Good
Reverse Frames: "
Floors: not seen
Keelsons: "

Stringers: Good
Inner Bottom Plating: ✓
State if Tanks have been examined inside: ✓
State if Tanks now tested: ✓
Bulkheads: Good
Ceiling: "
Cement ~~or Asphalt~~ (state which.): "
Rudder: "
Steering gear and its connections: "
Windlass: "
Have Pumps now been examined and found efficient? Not seen
Have Sluice Valves now been examined and found efficient? —
Have Watertight Doors now been examined and found efficient? —

Dblng. Plates under Sounding Pipes: ✓
Engine Room Skylights: Good
Coal Bunkers, Open'gs, Lids, &c.: "
Scuppers: "
Cargo Hatchways: "
Hatches: "
Planking of Wood Vessels: "
Caulking ditto: "
Treenails ditto: "
Breasthooks & Stemson ditto: "
Transoms, Pointers, & Crutches ditto: "
Timbers of Frame at openings ditto: "
Ditto ditto at other places ditto: "
Stringers, Clamps & Shelfs ditto: "
Salting ditto (State if examined.): "

Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month ..... Year .....
Boats: Good
Masts, Yards, &c.: "
Condition, how ascertained: from dk
(State if wedges removed): No
Sails: ✓
Equipment letter .....
Anchors, No. of: 3
Cables (State if now ranged): No
" length (on board): ✓ size: ✓
" Rule length (per Table 22): ✓ size: ✓
Hawser & Warps: Sufficient
Standing & Running Rigging: Good

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,07," or "to remain as classed and to have record of survey, 1,07, and the notations of *ss No.* 1-07 and ptND07, &c."

This vessel as seen is in efficient condition & is eligible in my opinion to remain as classed with fresh record of survey 12-08.

	£	:	:
Survey Fee (per Section 28)			
Special Damage or Repair Fee (if any) (per Sec. 28) — Lower 10%	1	19	0
Travelling Expenses (if chargeable)	1	10	0
Second Surveyor's Fee (if any)			

Fees applied for, 29 DEC 1908 19.....

Received by me, 5. 1. 19 09

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute LIVERPOOL 29 DEC 1908

Character Assigned 100 A1 record 12-08. Steam trawler

When Fee is Paid.

WA81-0099

10m.1.8.—Transfer Ink. (The Surveyors are requested not to write on or below the space for Committee's Minute.

Is Certificate required? If so, to be sent to

© 2021 Lloyd's Register Foundation