REC'D NEW YORK Mar 3-1919. (Received at London Office THU 20 MAR 1919 No. 20

REPORT of SURVEY for REPAIRS, &c.

of writing Report 27th Feb 1919 When handed in at Local Office ..... 191.... Port of Savannah Ga

in Survey held at Charleston & Savannah Date, First Survey 6th Nov 1918 Last Survey 7th Feb. 1919

Steel Steamer on the Wood, ~~Iron or Steel~~ Auxiliary Screw & Mast Schr "Verdun" (No. of Visits) Master J. L. C. Guesdon

TONNAGE:— Built at Savannah Ga By whom ~~Lev.~~ Eng & Construction Co. When 1918. YEAR. 19 MONTH.

GROSS 1352.19 Owners French Government Port belonging to Havre

UNDER DK. 1221.21

NET 831 ~~830.64~~ Owners' Address " " "
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Navy Yard Destined Voyage Havre

B=CellDBorDBa ..... feet; uE&B ..... feet; f ..... feet;
al capacity ..... tons. FPT ..... tons; APT ..... tons; MT ..... feet ..... tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides e tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ers, and of the inner bottom plating, especially in the boiler space.

Last Report, No. ..... Port .....

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expires.	Machinery and Boiler Surveys (including date of N.B., if any).
✠12 A.1. ~~Completed~~		+LMC-10.18
10.18.		+NDB-10.18.
Oil Engines		

Society's Freeboard (if assigned) as painted on Ship and now verified ..... ft. ..... ins.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case. .....

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR the purpose of ascertaining the nature and extent of the damage stated to have been caused by striking bank on opposite side of river immediately after leaving ways on day of launch.

On examination of the vessel while in dry dock at Charleston Navy Yard Charleston S.C. Found:- Sternpost at lower gudgeon to be spongy and leaking badly.

Recommended that defective part of stern post be cut out and scarfed with new timber, that 6" band be fitted round scarf and that band on bottom gudgeon be increased in depth from 3½" to 6" and that same band be carried 6" further inboard.

Small caulking repairs on hull made good.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

..... of Decks .....
..... ways .....
..... ngs .....
..... & Fastenings .....
..... e Plating .....
..... ng of ditto .....
..... hooks & Crutches .....
..... oms .....
..... is .....
..... se Frames .....
..... ms .....

Stringers .....
Inner Bottom Plating .....
State if Tanks have been examined inside .....
State if Tanks now tested .....
Bulkheads .....
Ceiling .....
Cement or Asphalt (State which.) .....
Rudder .....
Steering gear and its connections .....
Windlass .....
Have Pumps now been examined and found efficient? .....
Have Sluice Valves now been examined and found efficient? .....
Have Watertight Doors now been examined and found efficient? .....

Dblng. Plates under Sounding Pipes .....
Engine Room Skylights .....
Coal Bunkers, Open'gs, Lids, &c. .....
Scuppers .....
Cargo Hatchways .....
Hatches .....
Planking of Wood Vessels .....
Caulking ditto .....
Treenails ditto .....
Breasthooks & Stemson ditto .....
Transoms, Pointers, & Crutches ditto .....
Timbers of Frame at openings ditto .....
Ditto ditto at other places ditto .....
Stringers, Clamps & Shelfs ditto .....
Salting (State if examined.) ditto .....

Copper, or Y.M. of Wood Vessels (State if on Felt.) .....
When put on, Month ..... Year .....
Boats .....
Masts, Yards, &c. .....
Condition, how ascertained .....
(State if wedges removed) .....
Sails .....
Equipment letter .....
Anchors, No. of .....
Cables (State if now ranged) .....
,, length ..... size .....
(on board)
,, Rule length ..... size .....
Hawser & Warps .....
Standing & Running Rigging .....

Boards to be examined & found efficient before vessel is delivered to owners

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of *ss No.* 1–15 and ptND15, &c."

This vessel is in good condition, eligible in my opinion to be classed as recommended by Surveyor in attendance during construction.

Fee (per Section 28) ..... £

Damage or Repair Fee (if any) (per Sec. 29) ..... £ $25.00

Travelling Expenses (if chargeable) ..... £ $38.00

Surveyor's Fee (if any) Jacksonville Surveyor £ $15.40

$78.40

Fees applied for, ... 19....

Received by me, ... 19....

Geo. Allan

Surveyor to Lloyd's Register of Shipping.

Committee's Minute New York MAR 4 1919

Character Assigned 12 A1 Elec Lt subject

TUE. 2—SEP. 1919

TUE. 7—OCT. 1919

To Certificate required? If so, to be sent to .....

© 2021 Lloyd's Register Foundation W796-0027