Rpt. 8. (Received at London Office MON. MAR. 31. 1913 No. 3269

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 28/3/ 1913 When handed in at Local Office 28/3/ 1913 Port of Trieste

No. in Reg. Book. Survey held at Trieste Date, First Survey 20/3/13 Last Survey 22/3/ 1913 (No. of Visits three)

27 25" on the ~~Wood, Iron or~~ Steel S S "Sabbia" Master

TONNAGE:— GROSS 2752 DK. 2524 1237 Built at Port Glasgow By whom Clyde S B Eng Co When YEAR 1908 MONTH 8

Owners Nav Libera Triestina Soc in Azioni (E Pollich) Port belonging to Trieste

Owners' Address (if not already recorded in Appendix to Register Book).

...ed Afloat or in Dry Dock? Both Name of Dock Ansonia Destined Voyage Fiume

...ellDBorDBa 116' feet; uE 18 feet; f 13½ feet; ...pacity 684 tons. FPT tons; APT 54 tons; MT feet tons.

...-All alterations in the existing records should be underlined.

...e vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides ...s examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, ...d of the inner bottom plating, especially in the boiler space.

...Report, No. 7989 Port Rol

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
✠ 100 A1		✠ LMC 4.08
8.12		TS 6.11

Society's Freeboard (if assigned) as painted on Ship and now verified 3 ft. 8 ins.

...Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the ...Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs ...t of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; ...s being detailed in the body of the report, should be summarised in the form shown below. Whenever the ...nt of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on ...of this form. State also the dates and initials of any letters respecting this case.

...cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were ...i? Was a damage report made by anyone else? If so, by whom?

...OR EXAMINATION AS PER RULE, FOR Part S S W.

...l placed in dry dock, bottom and rudder examined, cleaned & coated, Holds, peaks, E & B ...E & B spaces, Bunkers cleared, ceiling lifted as per rule, all double bottom tanks examined ...ly, all holds, bunkers & peaks examined, Air Sounding pipes examined, also windlass, ...gear (hand & steam) masts, spars & general equipment, anchors, cables stated complete, water-...ors, hand pumps examined & found in order, decks, hatches in position examined, freeboard ...

Complete survey :- All double bottom tanks to test. F/pk Peak tank to examine & test.

...work effected to welding in shell in Fore Hold also shell caulking.

DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
... ...								
...and Faired or Repaired								
...r Repaired in place								

...DITION OF THE ... Good ...cks ... " ... " ...nings ... " ... " ...o. ... " ... " ...Crutches ... " ... " ... " ... " ... " ... " ...

Stringers Good
Inner Bottom Plating "
State if Tanks have been examined inside Yes
State if Tanks now tested No
Bulkheads Good
Ceiling "
Cement or Asphalt Cement (State which.)
Rudder Good
Steering gear and its connections "
Windlass "
Have Pumps now been examined and found efficient? Yes
Have Sluice Valves now been examined and found efficient? ✓
Have Watertight Doors now been examined and found efficient? Yes

Dblng. Plates under Sounding Pipes Good
Engine Room Skylights "
Coal Bunkers, Open'gs, Lids, &c. "
Scuppers "
Cargo Hatchways "
Hatches "
Planking of Wood Vessels /
Caulking ditto
Treenails ditto
Breasthooks & Stemson ditto
Transoms, Pointers, & Crutches ditto
Timbers of Frame at openings ditto
Ditto ditto at other places ditto
Stringers, Clamps & Shelfs ditto
Salting (State if examined.) ditto

Copper, or Y.M. of Wood Vessels / (State if on Felt.) When put on, Month Year
Boats Good
Masts, Yards, &c. "
Condition, how ascertained examination
(State if wedges removed) no (double)
Sails good
Equipment letter H
Anchors, No. of 3 B 15 17
Cables (State if now ranged) no
" length (on board) stated in survey size
" Rule length
Hawser & Warps
Standing & Running Rigging Good

...l Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ...rvey, thus, for example:—"....to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of ..., 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of *ss No.* 1–11 and ptNDl1, &c."

It is submitted this vessel is worthy to remain as classed ...d of survey notation of S S W pending for completion of same.

Survey Fee (per Section 28) £ : :
Special Damage or Repair Fee (if any) (per Sec. 29) £ for 125 - : :
Travelling Expenses (if chargeable) £ : :
Second Surveyor's Fee (if any) £ : :

Fees applied for, 28/3/13 1913
Received by me, 1913

TUE. MAR. 31. 1913 FRI. OCT. 10. 1913

Bernard Ross
Surveyor to ~~Lloyd's Register of British &~~ Foreign Shipping

Committee's Minute FRI. APR. 4 — 1913 FRI. JUN. 20. 1913 TUE. AUG. 26. 1913

Character Assigned Deferred for comp. of N.1 + L.M. 6.3.13 Deferred Deferred

FRI. AUG. 28. 1914 TUE. JAN. 13. 1914 FRI. OCT. 3 — 1913 FRI. NOV. 21. 1913

10m.7.12.—Transfer In... (The Surveyors are requested not to write on or be... To Certificate required? If so, to be sent to

14478-0039

© 2015 Lloyd's Register Foundation