Messrs. Cochrane & Sons' Steam Trawler No. 590.

Equipment Number 4120.

The second stockless anchor supplied in this case is 6cwts 0qrs 24lbs in weight, instead of 6cwts as required by the Rules, but the weight of the cast steel head & pins, etc., is 3cwts 2qrs 6lbs, instead of the Rule weight of 3cwts 2qrs 25lbs, a deficiency of 19lbs, or about 5%.

It is submitted in view of the deficiency in the weight of the cast steel head supplied the anchor in question does not merit approval, and should be replaced by one of proper weight and test.

9. 1. 14

FRI. JAN. 9 — 1914

Anchor not approved.

9.1.14

© 2021 Lloyd's Register Foundation
W807-0105