Lloyd's Register of Shipping.

m.7,40.

Received by Chief Ship Surveyor..... Received from Chief Ship Surveyor.....

E 8 NOV 1940

L.A. (Rosario) 7261

VESSEL'S NAME "SHREWSBURY" Rpt. Cff No. 53666

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Action had been deferred for dry docking after grounding.

The ROSARIO Lloyd's Agents' Surveyor reports the vessel afloat, the 'tween deck bunkers examined on account of fire, and no structural damage found.

The CARDIFF Surveyors report the vessel placed in dry dock, bottom coated, and no damage found on account of grounding, as above.

Minor wear and tear repairs effected.

It is submitted the vessel is worthy to remain as classed with record of survey 10.40.

100A1
With fbd
10.40 Cff

WAS
6-11-40

Delete from S.R.L

Dry dkg (grounding).

© 2019 Lloyd's Register Foundation

W83-0024