

Sppl 8224

"Bakuin"

3. 11. 90

Patent cement in flat of bottom  
found blistered & repaired with  
Portland. Ballast Tanks should  
be entirely examined at an  
early opportunity



© 2018

Lloyd's Register  
Foundation