

Ham 3178 Rakuin 20.3.95

One plate on starboard bow in
3rd strake from keel slightly
flawed. Surveyor could not
definitely ascertain condition
of same + recommended this to
be again examined when vessel
next docks.



© 2018

Lloyd's Register
Foundation