

N.E.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Mast wedges to be removed: main spar & rigging examined
That the defective plates in Bumpers to main deck on Star
side & in V sheet be removed or satisfactorily repaired
That the peak tanks be tested

Ces. Dykes

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

sent on the 8th

