

Ship Surveyor 20-1-12 Received from Chief Ship Surveyor _____

SH SP Baku Standard Report Shc No. 879

the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

sement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
ed in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Condoling SS

This vessel has been examined in dry dock, the bottom and sides
examiné, cleaned and coated, rudder lifted and three upper pintles
renewed.

The S.S. No.2, due 2.01, has in no part yet been held and
when the case was before the Committee in October last, the
owners' proposal to complete the survey within a month or two was
proved.

The year of grace allowed by the Rules expires at the end of
February next.

It is submitted the vessel is worthy to remain as classed
subject to the S.S. No.2 being completed by the end of February next,
and the Owners should be advised accordingly.



20-1-12
© 2018

Lloyd's Register
Foundation