

*Capt*  
GIBRALTAR,

27th December 1914.

- - - - -  
& Co.

Messrs. Cruso & Mackintosh, Agents, and with the consent of the Owners of the British s.s. "BAKU STANDARD" surveyed the rudder of the above named vessel after lifting and removal of two upper pintles.

The pin holes in rudder lugs are much worn.

Recommend holes to be broached out ~~true~~ and new pins fitted in a satisfactory manner to be a good fit in hole.

*W. J. B. Beck*  
*W. J. B. Beck*

Engineer Commander R.N.,

Surveyor to Lloyd's Register and  
Lloyd's Agents.  
Gibraltar.