

25 SEP 1936

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "PAMIR" Rpt. Skm. No. 4300

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

The Stockholm Surveyors report the ship examined afloat and the requirements of a S.S.No.3, due 5,36, partly complied with.

Ceiling in hold partly renewed and some minor repairs carried out.

It is stated that the Survey will be completed at Copenhagen in a few days.

It is submitted action be deferred.

To complete the Special Survey - See Report.

36. 24.9.36. *[Signature]*
 PLATING to be DRILLED when vessel is 30 years old, or at next Special Survey thereafter.

The Surveyors should be informed it is 'concluded' that the requirements of the 2nd paragraph of Clause 11, Page 20 of the Rules have been complied with and that the standing rigging has been lifted and the service and parcelling stripped off the nips, bends and splices for examination etc., but they should be requested to state if this is so.

Rigging not lifted see letter 9.10.36



© 2018

Lloyd's Register Foundation