

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 10th February, 1955 When handed in at Local Office _____ 19____ Port of HAMBURG
No. in Reg. Book 72866 Survey held at Hamburg Date, First Survey 4th February Last Survey 9th February, 1955
(No. of Tons _____)

on the Wood-Lam-on-Steel M.V. "PAMIR"
Built at Hamburg By whom Blohm & Voss When 1905 MONTH 10
GROSS 3103 Owners Landesbank und Girozentrale Schleswig-Holstein Owners' Address _____
UNDER DECK 2788 Managers _____ (If not already recorded in Appendix to Register Book)
NET 2509 Port belonging to Lübeck

Surveyed Afloat or in Dry Dock? Both Name of Dock H.C. Stülcken Sohn Destined Voyage _____
Cell/D/Bor/D/Bo feet: u/B/B feet: f feet: _____
total capacity _____ tons: FPT _____ tons: APT _____ tons: MT _____ feet _____ tons.
only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 17957 Port Ant

Periodical Surveys, when held, must be reported in detail and reporting in the terms of the Rules and items remaining to complete the Survey should be signified. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and details being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is required, the particulars should be clearly stated in the space provided on the back of this form. State also the date and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and to whom and why they were declined. _____
no damage Was a damage report made by anyone else? if so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE FOR DOCKING.
NOW DONE:— Ship placed in floating dock. Shellplating, sternframe and rudder cleaned, examined and repaired. Ship undocked 5th February, 1955.

EXAMINED:— Weather decks, hatchways with their closing and securing appliances, ventilator and other deck openings, casings and superstructure bulkheads with their closing appliances, windlass, general equipment, main and auxiliary steering gear, No. 3 hold. (DEEP TANK)
All parts surveyed found or placed in good condition.
Minor repairs effected.

CONDITIONS OF CLASS:— Now done: Nil. Deferred: Sternframe (E.W. 12.51) specially to examined next docking.
This item has been specially examined and found efficient at this time.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...	/	/	/	/	/	/	/	/
Removed and Faired or Repaired	/	/	/	/	/	/	/	/
Faired or Repaired in place	/	/	/	/	/	/	/	/

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks <u>good</u>	<u>where exam. good</u>	<u>good</u>	<u>exam.</u>
Caulking of Decks <u>good</u>	<u>where exam. good</u>	<u>not exam.</u>	When fitted, Month _____ Year _____
Coamings <u>good</u>	<u>good</u>	<u>not exam.</u>	Boats <u>good</u>
Beams & Fastenings <u>good</u>	<u>good</u>	<u>good</u>	Masts, Yards, &c. <u>good</u>
Outside Plating <u>good</u>	<u>good</u>	<u>good</u>	Condition, how ascertained <u>from Deck</u>
Frames <u>where exam. good</u>	<u>good</u>	<u>good</u>	Equipment letter <u>X U in red</u>
Reversing Frames <u>not exam.</u>	<u>not exam.</u>	<u>not exam.</u>	Anchors, No. of <u>3B+1S</u>
Longitudinals	<u>not exam.</u>	<u>not exam.</u>	Cables (State if now ranged) <u>not ranged</u>
Transverses	<u>not exam.</u>	<u>not exam.</u>	length _____ mean diamr. _____
Floors <u>where exam. good</u>	<u>not exam.</u>	<u>not exam.</u>	Rule length _____ size _____
Koelers <u>where exam. good</u>	<u>not exam.</u>	<u>not exam.</u>	Chain Locker <u>not examined or efficient</u>
Stringers <u>where exam. good</u>	<u>not exam.</u>	<u>not exam.</u>	Hawsers & Warps <u>efficient</u>
Inner Bottom Plating <u>not exam.</u>	<u>not exam.</u>	<u>not exam.</u>	Standing and Running Rigging <u>not exam.</u>
Have the Tanks been examined internally? <u>no</u>	<u>not exam.</u>	<u>not exam.</u>	Sails <u>not exam.</u>
Have the Tanks been tested? <u>no</u>	<u>not exam.</u>	<u>not exam.</u>	

General Observations, Opinion as to Class, Recommendation, &c. :
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example, "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of st No. 1-38."

This ship, so far as now surveyed, is eligible in my opinion to remain as classed with fresh record of Survey 2.55, subject to all conditions at present attached to the ship's class being dealt with as previously recommended.

Survey Fee (per Section 22) DOCKING DAY : 120.- Fees applied for, 29.2.1955
Special Damage or Repair Fee (if any) _____
Travelling Expenses (if chargeable) DAY : 10.- Received by me, _____
Second Surveyor's Fee (if any) _____
Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUESDAY - 5 APR 1955
Character Assigned Deleted notation Laid up
write Nam (spl)
W. J. Zerkson
W. J. Zerkson