

The class is subject to confirmation that a propeller of approved design has been fitted

5 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "PAMIR" REPORT Bmm No. 1473

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Survey

~~DAMAGE & WEAR AND TEAR.~~

Repairs, OS-advanced. An emergency battery requires to be replaced & the Surveyor recommends this be noted as an Endorsent B.

It is submitted the vessel is eligible to remain as classed, with ~~record of survey~~ subject as above, as recommended, with Endorsent B.

Endorsent B: - Emergency battery to be renewed.



Lloyd's Register Foundation



©2018

JAN 1956