

one

21st August, 1956.

one

HAMBURG.

4954 "INDIAN RESOURCE" This vessel's refrigerating machinery installation has today been classed Lloyd's RMC. 6.56 "to maintain temp. 20°F, with sea temp. 86°F maximum."

4808, 21, 67, 78, 79, 80, 915, 26, 36 - As recommended.

4893 "PAMIR". As recommended. I shall be glad to learn the reason why all the chain cable on board was tested. At the same time please inform me whether the Endorsement 'B' regarding the renewals of the emergency battery may now be deleted.

Classification Certificates in respect of the hull and machinery are being withheld pending your reply.

"GYPSUM EMPRESS". I acknowledge receipt of your letter of the 2nd inst., the contents of which have been noted. It is concluded, but I shall be glad to receive your confirmation, that heating surface given for Economisers is the whole surface for one boiler, in which case the heating surface of the boilers is 6852 square feet in accordance with Circular 1986