

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

4th March, 1930.

Dear Sir,

I have to acquaint you that in July last the Society's Surveyors at Rotterdam reported that the barque "PASSAT" had been placed in drydock in loaded condition and on account of damage through collision, partially lifted and repairs effected. The underwater parts were examined by a diver who reported that the shell plating on the port side was indented. Two beams in the hold were found bent but no signs of leakage. Temporary repairs were effected and the Surveyors recommended that the vessel should be placed in drydock for further examination and repairs.

It would appear from the Shipping Papers that the vessel arrived at Ghent on the 21st ultimo, and in the circumstances I shall be glad if you will ascertain and let me know what arrangements the Owners propose making in the matter.

I am, Dear Sir,

Yours faithfully,

A. Chisholm, Esq.

HAMBURG.

pro Secretary

P.S. You will observe that the 2nd Special Survey No. 2 will become due at the end of this month.



© 2018

Lloyd's Register
Foundation