

E X T R A C T      from Ham. Cl. Ltr. 25.11.55.

MC. 4323, 24. As recommended.

4283. As recommended.

I think it well to point out that the class of this ship was subject to the stern frame (E.W. 12,51) being specially examined at the next drydocking. In view of the fact that the electrically welded repairs to the stern frame were examined at this time and found to remain efficient, I shall be glad to learn whether the condition of class in respect of this item might now be deleted.

Please also confirm that the evaporator safety valves have been adjusted under steam.

Classification Certificates in respect of the Special Survey of hull and machinery are enclosed for transmission to the Owners, provided the above mentioned matters are in order.



© 2018

Lloyd's Register  
Foundation