

31st July, 1956.

one

HAMBURG

4854, 64, 97 - As recommended.

"PASSAT" I acknowledge receipt of your letter of the 16th instant and in view of the contents the condition of class has been amended to "Repairs to propulsion motor supercharger clutch being verified on return to home port" and I shall be glad if you will advise the Owners accordingly.

ENEARN" 4887 HMC As recommended.

"INDIAN PIONEER" Before your report No. 4888 receives the consideration of the Committee I have to inform you that it appears that the port and starboard diesel oil D.B. tanks (situated inboard of the port and starboard 4B D.B. fuel oil tanks) require to be examined and tested to complete the Special Survey, and your comments are requested in this matter. At the same time please state if all the items to complete the Continuous Survey of the Machinery listed in my letter of 23rd May last have been surveyed including combustion control air receivers.

Lloyd's Register
Foundation