

Report of Survey for Repairs of Engines and Boilers.

No. 156

(Received at London Office,)

No. in Reg. Book. 974 Survey held at Antwerp Date, first Survey 26th June Last Survey 26th June 1882
 on the Machinery of the Steamer N. S. Annie (Number of Visits one)
 Tonnage, Gross 443 Built at Hull When built 1864
 Ditto, Net 274 Owners Goolc Steam Ship Co. Port belonging to Goolc
 Diameter of Cylinder 30 and 54 3/4 Engines made by M. Samuelsen Hull When made 1870
 Length of Stroke 24 inches Boilers made by C. D. Holmes When made 1874
 Pressure of Steam 60 lb
 Registered Horse Power 98
 Last Survey No. 5135 Port Hull
 Surveyed Afloat or in Dry Dock (State name of Dock.)
 Years assigned. + Character in Register Book. A

Particulars of Repairs and Examination.

(State cause of Repairs.)

Referring to my report N^o 122 dated 2nd January last. At the request of Captain Spink I repaired this day on Board the above named Steamer for examination of Boilers.

On careful inspection all inside and outside, found the repairs effected in last January, notably in flame chest back, standing well and the actual Condition of Boilers satisfactory. Working pressure reduced and safety valves set to 50 lb per square inch.

General Observations, Opinion, and Recommendation:— I am of opinion that the said Boilers are still, at present, in an efficient state but recommend the re-surveying of same after six months from this date.

Entry or Registering Fee. £ : :
 Survey Fee (per Section 28) £ 2 : 2 : 0 received by me,
 Certificate (if required) £ : : 26th June 1882
 to be sent as per margin.
 (Travelling Expenses, if any, £)

Committee's Minute

Tuesday, 11th June, 1882.

Assigned B. S. D. 02

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2018
 Lloyd's Register
 Foundation

No. submitted that this vessel is
eligible to have the notification
of 6.8 recorded, subject to
the boilers being reassured
in due month

14/29/6/82



© 2018

Lloyd's Register
Foundation