

Received by Chief Ship Surveyor 6.6.11

Received from Chief Ship Surveyor

VESSEL'S NAME

Miss Stetten

Rpt.

Lth

No.

13352

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

4^d S.S. No. 2

4^d
The S.S. No. 2 has now been held, and the following repairs done (due to wear & tear):- the reverse frame on 6 floors & 5 plates in tunnel recess renewed & minor repairs carried out. 2 lengths of cable renewed. Bottom cleaned & coated.

It is submitted the vessel is worthy to remain as classed, with record of Survey 5.11 and notation of S.S. Lth No 2-11 as recommended.

A-1.

5.11 Lth

S.S. Lth No 2-11

JW

6.6.11