

REPORT of SURVEY for REPAIRS.

31268

No. in Reg. Book. 142 No. 30500 Survey held at London Date, first Survey 19th July Last Survey Nov^r 2nd 1870
 on the Ship Thermopylae Master Robt^t Remball
 Tonnage 944 built at Aberdeen When built 1868
 By whom built Hood Owners Thompson & Co.
 Port belonging to Aberdeen Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Canal Dry dock
 Last Survey, No. 30500 Port Loon Classed 14. A. 1.
11. 69

REPAIRS, &c.

*Stripped off the Yellow metal
 examined the caulking, and re-sheathed
 with Yellow metal.*

Present Condition of the

Decks	<i>good</i>	Freemasts	<i>bolts where seen good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	<i>firm</i>	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<i>from the Deck</i>
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors	No. of <i>3 & 1 S. 2 K.</i>
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	<i>efficiently</i>	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>Tell^r Melt When put on Now</i>	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	<i>good</i>	Cargo and Main Hatchways	<i>good</i>
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	"	Hatches	<i>good</i>
Scuppers	<i>good</i>				

General Observations and Opinion,

*She is in good condition and I am of opinion
 is entitled to remain as class'd
 14. A. 1.
 Samuel Resons*

The Amount of Entry Fee.....£ — : — : is received by me;

Special..... 1 : 1 : }

Certificate (if required).....

Committee's Minute *9th December* 18 *70*

Character assigned *17th record Melt*



© 2018
 Lloyd's Register
 Foundation