

The Hong Kong Surveyor should be
informed that owing to this vessel's
condition, as reported by the Society's
survey at Victoria B.C. it is
considered that upon her arrival
at Hong Kong she should be at once
placed in dry dock, the metal
stripped & her bottom thoroughly caulked,
dredged & remetalled. He should also
be informed that the Special survey
required by the Rules to be held on
foreign vessels every 4 years
& set forth in par. 43, pages 92 & 3
(Foreign Rules) and which became
due in December last should be
carried out at Hong Kong, in order
to enable her to obtain her Certificate
from the R. B. C.

Ltr to M.K. 10/6/92.

C.B.



10-6-92
© 2018

Lloyd's Register
Foundation