

# ANNUAL SURVEYS.

31

No. 913 on the Ship Cutty Sark Survey held at London Date 18<sup>th</sup> Oct<sup>r</sup> 24<sup>th</sup> 1890  
 Tonnage 921 Built at Dumbarton Master Moodie When built 1869 <sup>11<sup>th</sup> month</sup>  
 By whom built \_\_\_\_\_ Owners S. Willis  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Grand Upper Dock & East India Docks

Last Survey, No. 3077 Port of Glasgow Classed 16. A. 1.  
1/0

The present Condition of the

Decks	<u>Good</u>	Treenails <u>Bolts where seen</u>	<u>Good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Poisters, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors No. of <u>3 &amp; 18, 2 H</u>	"
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder <u>efficient</u>	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper <u>1st Metal</u> When put on <u>1869</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good  
 Repaired the Yellow Metal Sheathing. The copper butts on the port side  
 She appears (as far as seen) to be in good condition. and Boats skid from damage.  
 Same of opinion she is in as  
 Classd 16. A. 1.

Committee's Minute 28<sup>th</sup> October 1890  
 Character assigned 1st 1st

