

EXTRACT OF BREMEN REPORT 9 NUMBER 5053 dated 15/2/61.

Note:- As regards the RS on the vessel's refig. cargo installation, due 1/61 it was now learned from the Owners that they will request for this class being withdrawn due to the fact that the refig. cargo spaces are never being used. An official letter to this effect will be sent to this office and this will be sent to London Office in due course.



© 2018

Lloyd's Register  
Foundation