

LLOYD'S REGISTER OF SHIPPING

65/7652

Port..... B r e m e nDate..... 17th May, 1965

This is to Certify ^{we} that ~~I~~ have surveyed part of the machinery of the M/V "BERLIN" 18600 gross tons of Bremen for TS(CL), DBS and CSM whilst she lay afloat and in dry dock at Bremerhaven on the 19th May, 1965 and subsequently to the 12th May, 1965

and that all ~~our~~ ^{our} recommendations have been carried out to ~~our~~ ^{our} satisfaction. ~~I~~ ^{We} ~~are~~ reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following

survey records assigned CSM (with date) upon completion and DBS 5/65 when the safety valves of the port boiler have been adjusted under steam, subject to port screw shaft being specially examined in way of forward end of cone by the end of November, 1965 (record of TS(CL) p. 5/65 being withheld meantime) and to any outstanding conditions of Class being dealt with as previously recommended.

Parts now examined:— Propeller, port screw shaft and outside fastenings of sea connections.

Port and starboard donkey boilers
 Port and starboard exhaust gas boilers
 Starboard donkey boiler safety valves adjusted
 Starboard M.E. No. 2 crosshead and bearings
 Starboard M.E. Nos. 1, 2 and 5 crankpins and bearings
 Port M.E. No. 3 crosshead and bearings
 Port M.E. Nos. 1 and 4 crankpins and bearings.

(For K.H. Fedderwitz and self)


E. Schomber

Surveyor to Lloyd's Register of Shipping
 (E. Schomber and K.H. Fedderwitz)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that—
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2018

Lloyd's Register
 Foundation