

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

10th January, 1966

C.

DD/BN

Dear Sirs,

CLASSING LETTER

7899 "ASTRID ELISABETH". As recommended, except that a notation of SS(Dr 4 years) 11,65, has now been assigned.

A subsequent Report of survey carried out at Liverpool has now received the consideration of the Committee, as a result of which a notation of CSM 12,65 has now been assigned.

It is concluded that the SRL Appendix item regarding the port boiler inboard furnace deformation remains efficient, but your confirmation is desired.

7894 "BERLIN". As recommended except that a notation Port TS 5.65, has now been assigned.

According to the records in this Office, the following machinery items have not been seen for more than four years:-

Starboard Main Engine

No.6 crankpins and bearings.

Nos.4,5,6 & 7 journals and bearings.

Engine Test.

Port forward and port aft bilge pumps.

Starboard aft fuel transfer pump.

Port fuel service pump.

Starboard outer lubricating oil pump



© 2018

Lloyd's Register
Foundation

-2-

Forced circulating pumps
Air pump
Port oil burning pump.
Starboard steering pump.
Auxiliary air receivers.
Port inboard auxiliary engine
Centre auxiliary engine
Starboard inner auxiliary engine.

Port Main Engine

Nos. 4 & 5 connecting rods, top ends and guides.
No. 6 crankpins and bearings.
Engine Test.

In the circumstances, the Owners should be requested to make the necessary arrangements for these items to be surveyed as soon as possible.

Yours faithfully,

Cc Ham

pro Clerk to the
Classification Committee.

The Surveyors,
BREMEN



© 2018

Lloyd's Register
Foundation