

1
int to Chief Surveyors.....

Received from Chief Surveyors - 26 JUN 1947.

VESSEL'S NAME BELPAMELA REPORT N.Yk No. 47720**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER-SURVEYOR.**

In cases which have to be submitted to the Classification Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classification Committee may have all the salient points presented in the endorsement." —(Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey Repairs When due.....N O T E D

Subject to permanent repairs to indented bottom shell plates etc. in 'C' & 'D' strakes (p & s) and to bow shell plate (p.s) at the first convenient opportunity.

*OBM.
23.6.47.*

^{TANK TOPS}
Examination and testing of Nos. 1,2,3,4,5 & 6 D.B. tanks and fitting of new ceiling in cargo holds may be credited to S.S. if completed by 3.48.

6/11.

The vessel is later reported sunk in the North Atlantic.



© 2018

Lloyd's Register
Foundation