

Chief Surveyors _____

Received from Chief Surveyors _____

Ship's NAME Stl T.S. M/V MANUNDA Report Sls No. 49089**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Claiming Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Claiming Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

of Survey 1st Entry When due Revised Rules _____

✱ 100 A.I. (Steel). With Keeboard

30" (Stl - weather D^x leaks)

Cell D.B. 344' 11005, Tanks in way of tunnels 359t, F.P.T. 75t APT. 825.

F.K, 8 B.H. (Cell B.H. to Weather D^x, 6 B.H. to 2nd D^x, 1 B.H. to 3rd D^x)

pt Cem, Plyds A CP.

F 82'.



© 2018

Lloyd's Register
Foundation

25.4.29