

1
Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME S.H. J. S. VICEROY OF INDIA Report GL No. 48950

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Clashing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Clashing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 34592.)

Nature of Survey

1st Entry

When due

+ 100 A. 1 (steel) } Subject to a heavier anchor & two
with freeboard } lengths of chain cable being supplied
3 dks (steel-weather dk, tank 5) 4th & 5th dks (steel) in
forward holds and part after holds.

Call DB 534' 3039C. FPT 170C APT 138C.

FK. 11BH (1BH to weather dk 10BH to 2nd dk) ft Cons.

Lloyds A & CP

B 354' F 82'

Revised Rules

[Signature]

[Signature]



© 2018

Lloyd's Register
Foundation