



Lloyd's Register of Shipping.

18, NIHON OH-DORI, NAKA-KU,
(CHARTERED BANK BUILDING)
(P. O. BOX NO. 228).
YOKOHAMA, JAPAN

6th March, 1963

Your
Reference C
MWK/MRN

Dear Sir,

"ORIENTAL QUEEN"

We are in receipt of your Classing Letter
of the 26th ult.

In reply we wish to state that the existing
port screwshaft was tried in the lathe and found to be
bent at the taper and was renewed.

The identification marks on the new shaft are:-

" Lloyds No.257
RLA
14/2/36
B.T. 15/2/36 "

The marks on the condemned shaft were corroded
out.

This ship is fitted with a composite boiler
only, and the exhaust gas economiser was reported "Good"
in error.

These errors are regretted.

Yours faithfully,

For I. Suzuki & S. Takenaka

[Signature]
pro the Surveyors

The Secretary,
LONDON.

RRB/hy