

2

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Ste 1 1/2 Philadelphia

Report

N.Y.K. No. 21879

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Claiming Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Claiming Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 26.5.96.)

No. 2

SURVEY PARTLY HELD.

When due

12.21

When proposed to be completed

Portion of Survey held, &c.,

The Surveyors recommend in their report to the Owners that the survey be completed before the expiration of the year of grace in Decr. next.

To complete the survey. See report.

M

MD

8-8-72

It is concluded the vessel has 3 lower anchors and a stream anchor of sufficient weight on board but the Surveyors should be requested to state if this is so & also whether No 7 double bottom tank has been, or still requires to be, examined internally, as this is not clear from the report.

The Surveyors should also be requested to state whether the indented plating referred to in their report No 18246 has been dealt with & all repairs considered necessary, also effected to the indented plating on port side forward & aft and damage through fire at after end of saloon.

Dealt repairs to Tank top } MD
from S.R.L. 10.10.72

M

MD
368