

18 DEC 1943

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "EMERALD" REPORT Gl.s. No. 67830

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage ~~Repair~~

Subject to permanent repairs to set up bottom shell plating at the first convenient opportunity and to (a bower anchor and 30 fathoms of chain cable being supplied).

The Certificate of Classification to be endorsed "Cargo Bittens not fitted" and the same notation to be printed in the Register Book.

Wals  
17.12.43



© 2018

Lloyd's Register  
Foundation