

s.s. "CONTE ROSSO".

Loeffler Escher Wyss H.P. Installation.

IT IS SUBMITTED the Winterthur Surveyor
be informed it is noted that material tests have been
carried out on test pieces cut from forgings, including
the pinions and gear wheels for this installation.

With reference to the circulating pump
shaft and cast steel casing, the particulars of test results
obtained by the Makers, as shown on the photostatic copies
of test sheets forwarded with the Surveyors' letter, are
satisfactory and these parts can therefore be accepted.

It should be added that the Forging Report
No. F.867 mentioned in the Surveyors' letter does not appear
to have come to hand.

only an
auxiliary

These
ordered
were not
being tested

✓

Lup/11/35

[Signature] *[Signature]* *[Signature]*
1.11.35.



© 2018

Lloyd's Register
Foundation