

1

- 1 MAY 1940

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME LANCASTRIA

Report LIV

No. 114078

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

DAMAGE

When due

Subject to an internal examination of Nos 819 d.b. tanks and settling + storage tanks at the first convenient opportunity
(Repair test and replace 15 fms of chain cable) also subject to indented shell plate and framing in way, on port side forward in way of crew's quarters, being dealt with at the Owner's convenience.

WAB
6.5.40

E.S.D.



© 2018
Lloyd's Register
Foundation