

s.s. "MANCHESTER REGIMENT".  
-----

It is submitted the Manchester Surveyors be informed that it is observed from their Report C.11 received today that the tonnage opening, the freeing ports and scuppers in the tonnage well, and the tonnage openings and closing appliances in the bulkheads at the forward and after ends of the well have not been restored.

In these circumstances they should ascertain from the Owners if it is their intention to proceed with the restoration of these openings with a view to the exemption from tonnage measurement of the tween deck spaces, and the modification of the freeboards.



6.1.33.



© 2018

Lloyd's Register  
Foundation