

002038-002050-0048

1m, 10, 33.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "Gedvine"

Rpt. Rot


No. 27832

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey "First Entry Report"

It is submitted before this case reaches the consideration of the Committee, the Surveyors be informed it is concluded the thickness of the tank side brackets & the poop side plating respectively as approved, have not been departed from & that the latter has been incorrectly reported but they should state whether this is so & whether also the lower stiffeners fitted on the collision bulkhead are as approved. The Surveyors should be reminded that any departures from the approved plans should be noted in the Report in the column provided for the purpose.



H.W. 17.2.39

Middle Line Keelson, on Floors, Angles, } ✓

R.L.P. Second Deck, amidships, Angle, [] or []

5 1/2 x 3 x

3
3
2 3/4 x
2 3/4 x
12
11
"
flor
pl
ave
3 x
22